


V	VOLVO STANDA				TENANCE PROCE	DURE			SMP Nº : 0002		
TATION	TATION: 2V11 TASK SMP : MONTHLY INSPECTION (ASK SMP : MONTHLY INSPECTION OF	F V11=V01WR1 WEISS TURNTABLE			VALIDATION / STAMP		TIME (min):	36	
SUB-SYS	STEM:	AUTOMATE	D CELL - BODYSIDE SUB		MAN POWER 1 SAFETY				Created: 12/01/2022 Review: Frequency (x/year): 12		
EDGER	СОМР	PONENTS :									
		MA	NDATORY PPE:	SPECIFIC PPE: No special PPE be	eyond standard for this check.	4	HAZARDS: Electric	ity, Pinch Points, Air		•	
STEP	ITEM		INSTRUCTION		HAZARD	SAFE	TY PROCEDURES	TOOL	PARAMETER	ACTION (min	
1		Lock out rob			A	E	X	LOCK	UNABLE TO START CELL	1	
2	1	gear motor's	ect entire Weiss turntable unit. Pay ext connections for any damaged or expo- connections as necessary.	4		<u> </u>	VISUAL	GOOD CONDITION	3		
3	2	mounting bo	ect the Weiss Turntable's gear motor, i lts and verify they're aligned. Retighter	4	<u> </u>		VISUAL / TORQUE WRENCH	GOOD CONDITION	5		
4	3		ect the Weiss Turntable's service union , damaged cables, or exposed / fraying /.	4		<u> </u>	VISUAL	GOOD CONDITION	5		
5		Visually insp fittings if neo	ect the fittings attached to the service cessary.	4			VISUAL	GOOD CONDITION	5		
6			ect lubrication level of the Weiss Turnt rication procedure as required.	able's gear motor. Perform oil	4	TOOL KIT, LUBRICATIO DRAIN PAN			GOOD CONDITION / LUBRICATED	15	
7			ect turntable unit for excessive build u ed solvent to remove any excessive dir		4		<u> </u>	VISUAL	GOOD CONDITION	2	
8											
9											
10											
11											
12											
13											



VOLVO			STANDARD MAINTENANCE PROCEDURE							SMP N°: 0002	
STATION	STATION: 2V11		TASK SMP: MONTHLY INSPECTION OF V01WR1UQ51 / V01WR1UQ53 GEO FIXTURE				VALIDATION / STAMP		TIME (min):	28.5	
SUB-SYS	STEM:	AUTOMAT	FED CELL - BODYSIDE SUB				ENG		Created: 12/01/20	22	
					MAN POWER	1	SAFETY		Review:		
LEDGER	COMI	PONENTS :	:						Frequency (x/yea	r): 12	
			MANDATORY PPE:	SPECIFIC PPE: No special PPE b	eyond standard for this check.	and standard for this check. HAZARDS: Electricity, Pinch			Points, Air, Robot Movement		
						4	. 📤				
STEP	ITEM		INSTRUCTION		HAZARD	SAFE	ETY PROCEDURES	TOOL	PARAMETER	ACTION (min)	
1		approved	spect both Geo Fixtures for any damage o cleaning agent to remove any weld spatter	4		<u> </u>	CLEAN RAG CLEANING SOLUTION	GOOD CONDITION	1		
2		connection	spect all electrical connections on both G ns are free of cuts, fraying, and exposed w ns with identical components.	4	<u>"</u>		VISUAL	GOOD CONDITION	2.5		
3	2		spect all locator pins on the Geo Fixtures , replace the locator pins with identical co	4		<u> </u>	VISUAL	GOOD CONDITION	5		
4	3		spect the Turck inductive and proximity so ne inductive and proximity sensors with ide	4		<u> </u>	VISUAL	GOOD CONDITION	5		
5			spect the pneumatic connections and air any leaking air or damaged connections.	4		<u> </u>	VISUAL	GOOD CONDITION	5		
6			spect the clamping elements on the geo fi rking condition. Replace the clamping ele	4		<u> </u>	VISUAL	GOOD CONDITION	5		
7	6	Inspect the with an ide	ne pneumatic cylinders for any damage or leaking air, replace the cylinder entical one if leaking air is found.		4		<u> </u>	VISUAL	GOOD CONDITION	5	
8											
9											
10											
11											
12											
12											



V	DL	VO		STANDARD MAINTENANCE PROCEDURE					SMP N°: 0002	
STATION	N: 2V1 1	1	TASK SMP : MONTHLY INSPECTION OF \	/01WR1UQ52 GEO FIXTURE			VALIDATION / STAMP		TIME (min):	24
SUB-SY	STEM:	AUTOMAT	ED CELL - BODYSIDE SUB				ENG		Created: 11/29/20	22
					MAN POWER	1	SAFETY		Review:	
LEDGER	R COMI	PONENTS :							Frequency (x/year	r): 12
		N	MANDATORY PPE:	SPECIFIC PPE: No special PPE b	eyond standard for this check.		HAZARDS: Electricity	, Pinch Points, Air,	Robot Movement	
	30					4				
STEP	ITEM		INSTRUCTION		HAZARD	SAFE	TY PROCEDURES	TOOL	PARAMETER	ACTION (min)
1		and a plan	spect the Geo Fixture for any dirt, debris, on the deprious the tapproved cleaning solution to remove the ture.	4	CL		CLEAN RAG CLEANING SOLUTION	GOOD CONDITION / CLEAN	1	
2	2	any loose	spect the Tunkers clamping elements loca components, worn clamps, fraying or expo required, replace the clamping elements v	4		<u> </u>	VISUAL	GOOD CONDITION	5	
3		have any o	spect the Misumi locator pins and verify the other outstanding damage. If required, repless.	4		<u> </u>	VISUAL	GOOD CONDITION	2	
4		not broker	ually inspect the Welker shot pins for any damage or wear, verify the shot pins are thousand the shot pins with identical mponents.		4	<u> </u>		VISUAL	GOOD CONDITION	5
5	5	any sound	spect the Welker shot pin cylinders locate s of escaping air, loose components, or ot eplace the Welker shot pin cylinders with i spect the pneumatic manifold mounted on	her outstanding damage. If	4		<u> </u>	VISUAL	GOOD CONDITION	5
6	6	solenoid v	alves, electrical connections, and air lines age.	are all free of damage, wear, or	4		<u> </u>	VISUAL	GOOD CONDITION	5
7	7		spect the Turck inductive sensors for any and a plant approved cleaning solution to a ensors.		4		<u> </u>	CLEAN RAG CLEANING SOLUTION	GOOD CONDITION / CLEAN	1
8										
9										
10										
11										
12										



VOLVO STANDARD MAIN					TENANCE PROCE	SMP N°: 0002				
STATION	STATION: 2V11		TASK SMP : MONTHLY INSPECTION OF V01WR1UQ54 GEO FIXTURE			VALIDATION / STAMP		TIME (min):	24.5	
SUB-SY	STEM:	AUTOMAT	ED CELL - BODYSIDE SUB				ENG		Created: 11/29/20	22
EDGER	СОМР	PONENTS :			MAN POWER	1	SAFETY		Review:	
			MANDATORY PPE:	SPECIFIC PPE: No special PPE be	eyond standard for this check.	4	HAZARDS: Electricit	y, Pinch Points, Air	Frequency (x/yea , Robot Movement	•
STEP	ITEM		INSTRUCTION		HAZARD	SAFE	TY PROCEDURES	TOOL	PARAMETER	ACTION (min)
1	1	and a plan	spect the Geo Fixture for any dirt, debris, t approved cleaning solution to remove th ture.	4		<u> </u>	CLEAN RAG CLEANING SOLUTION	GOOD CONDITION / CLEAN	1	
2	2	any loose	spect the Tunkers clamping elements loca components, worn clamps, fraying or expo required, replace the clamping elements v	4		<u> </u>	VISUAL	GOOD CONDITION	5	
3	3	componen	spect the Welker shot pins for any damagets. If required, replace the Welker shot pin	4		<u> </u>	VISUAL	GOOD CONDITION	5	
4	4	the pins ar		4		<u></u>	VISUAL	GOOD CONDITION	5	
5	5	connection	spect the Welker pneumatic cylinder for and ns, or other outstanding damage. Replace entical component if required.	4		<u> </u>	VISUAL	GOOD CONDITION	5	
6	6	build up or	spect the Turck inductive sensors for any n the sensor. Use a clean rag and a plant a y build up from the sensor.	4		<u> </u>	CLEAN RAG CLEANING SOLUTION	GOOD CONDITION / CLEAN	1	
7		Restore ro	bot cell to operational state.						EQUIPMENT READY / NO ALARMS	2.5
8										
9										
10										
11										
12										

